

ASSESS	Assess					
g-shift						
f-shift						
unshifted	NXTFIT	-ZOOM ₀				
Page 1	F1	F2	F3	F4	F5	F6

Prev menu https://47calc.com/doc/C47/Menus/C47_Menu_Area_page_1.pdf

Next menu https://47calc.com/doc/C47/Menus/C47_Menu_AUDIO_page_1.pdf

Level	Label	Type	FullName	Extended description	Category	Flag	Catalog	Default
Menu p1	ASSESS	MENU (item)	Assess	Display graphical assessments of the selected regression curves	Plotting and curve fitting			
F1	NXTFIT	Command (cyclic, nonpgm)	Next fit	Assess next curve fitting (cyclic)	Plotting and curve fitting			
F2	-ZOOM ₀	Command	Zoom out on y-axis	Decrease zoom level on the y-axis (range -16 to +16) ; Info : <0 : zoom out ; 0 : normal ; >0 : zoom in ; -ZOOM resets ↑Y and ↓Y to zero	Plotting			0
F3								
F4								
F5								
F6								
fF1								
fF2								
fF3								
fF4								
fF5								
fF6								
gF1								
gF2								
gF3								
gF4								
gF5								
gF6								