

SCATR	Scatter plot					
g-shift						
f-shift						
unshifted	CENTRL	S _{mi}				
Page 1	F1	F2	F3	F4	F5	F6

Prev menu https://47calc.com/doc/C47/Menus/C47_Menu_S-INTS_page_1.pdf

Next menu https://47calc.com/doc/C47/Menus/C47_Menu_SecPrp_page_1.pdf

Level	Label	Type	FullName	Extended description	Category	Flag	Catalog	Default
Menu p1	SCATR	MENU (item)	Scatter plot	Scatter plot of measurements (programmable) ; Info : CENTRL (re)starts menu SCATR ; when SDIGS is set to the maximum value of 34, plotting uses 15 instead, otherwise it uses the value set by SDIGS	Measurement		SCATR	
F1	CENTRL	Command (submnu)	(Plot) Central	Orthogonal curve fit and show parameters, requires 30 data pairs ; Info : Opens the graph mode and (re)starts menu SCATR	Measurement		CENTRL	
F2	S _{mi}	Command	Precision	Precision of measuring instrument investigated, requires 30 data pairs -- see https://blog.minitab.com/en/real-world-quality-improvement/orthogonal-regression-testing-the-equivalence-of-instruments ; TI : S _{mi} =	Measurement		S _{mi}	
F3								
F4								
F5								
F6								
fF1								
fF2								
fF3								
fF4								
fF5								
fF6								
gF1								
gF2								
gF3								
gF4								
gF5								
gF6								