

CENTRL (SCATR)	(Plot) Central					
g-shift						
f-shift						
unshifted	CENTRL	S _{mi}				
Page 1	F1	F2	F3	F4	F5	F6

Prev menu

https://47calc.com/doc/R47/Menus/R47v0_Menu_Cauch_page_1.pdf

Next menu

https://47calc.com/doc/R47/Menus/R47v0_Menu_CFLG_page_1.pdf

Level	Label	Type	FullName	Extended description	Category	Flag	Catalog	Default
Menu p1	CENTRL (SCATR)	Command (submnu)	(Plot) Central	Orthogonal curve fit and show parameters, requires 30 data pairs ; Info : Opens the graph mode and (re)starts menu SCATR	Measurement		CENTRL	
F1	CENTRL	Command (submnu)	(Plot) Central	Orthogonal curve fit and show parameters, requires 30 data pairs ; Info : Opens the graph mode and (re)starts menu SCATR	Measurement		CENTRL	
F2	S _{mi}	Command	Precision	Precision of measuring instrument investigated, requires 30 data pairs -- see https://blog.minitab.com/en/real-world-quality-improvement/orthogonal-regression-testing-the-equivalence-of-instruments ; TI : S _{mi} =	Measurement		S _{mi}	
F3								
F4								
F5								
F6								
fF1								
fF2								
fF3								
fF4								
fF5								
fF6								
gF1								
gF2								
gF3								
gF4								
gF5								
gF6								