

CENTRL	(Plot) Central MENU	Orthogonal curve fit and show parameters, requires 30 data pairs	Category: Measurement
---------------	---------------------	------------------------------------------------------------------	-----------------------

Menu	CENTRL	1	2	3	4	5	6
3	gShifted						
2	fShifted						
1	primary	CENTRL	S_{mi}				
Page	1	F1	F2	F3	F4	F5	F6

<i>Info</i>	CENTRL (re)starts menu SCATR
-------------	------------------------------

CENTRL	Page 1								
F-key	Button label	Full name	Extended description	Type	Flag name	Additional information	Catalog	Default	Status
F1	CENTRL	(Plot) Central	Orthogonal curve fit and show parameters, requires 30 data pairs	Function (special)		Info : Opens the graph mode and (re)starts menu SCATR	CENTRL		
F2	S_{mi}	Precision	Precision of measuring instrument investigated, requires 30 data pairs [https://blog.minitab.com/en/real-world-quality-improvement/orthogonal-regression-testing-the-equivalence-of-instruments]	Function			S _{mi}		
F3	<empty>								
F4	<empty>								
F5	<empty>								
F6	<empty>								

fShifted F1	<empty>								
fShifted F2	<empty>								
fShifted F3	<empty>								
fShifted F4	<empty>								
fShifted F5	<empty>								
fShifted F6	<empty>								

gShifted F1	<empty>								
gShifted F2	<empty>								
gShifted F3	<empty>								
gShifted F4	<empty>								
gShifted F5	<empty>								
gShifted F6	<empty>								